COVERALL 3

FUNCTIONAL AND EFFECTIVE

Functional and versatile PVC goggles that fit over prescription glasses. Available in ventilated and sealed versions.







Clear with indirect vents top/bottom: 1686101



Smoke with indirect vents top/bottom: 1686102



Platinum Clear Vents Fully Sealed: 1687101



Platinum Smoke Vents Fully Sealed: 1687102



- **+** ECONOMIC MODEL
- + ADJUSTABLE NYLON STRAP
- + FITS OVER PRESCRIPTION GLASSES
- + 2 VERSIONS VENTILATED OR SEALED
- + ♦ PLATINUM COATING (→P)



COVERALL 3

FUNCTIONAL AND EFFECTIVE

MODEL	VERSIONS	REFERENCES	LENS MARKING	FRAME MARKING	COATINGS
COVERALL	Clear	1686101	CIO	AS/NZS 1337.1.2010	Anti-scratch/Anti-fog
	Smoke	1686102	Cl3	AS/NZS 1337.1.2010	Anti-scratch/Anti-fog
	Platinum Clear Vents Fully Sealed	1687101	CIO & ⁺ ₽	AS/NZS 1337.1.2010	Anti-scratch/Anti-fog/Platinum +→
	Platinum Smoke Vents Fully Sealed	1687102	Cl3 & ⁺₽	AS/NZS 1337.1.2010	Anti-scratch/Anti-fog/Platinum ⁺₽

LENS MARKING

- **→.** Platinum is permanent coating on both sides of the lens gives them a high resistance to scratching (1.4 cd / m²), to the most aggressive chemicals and delays the onset of fogging for 2 minutes, as per the testing requirements of EN166.
- I. The letter 'I' signifies 'Medium Impact' approval.
- O. The letter 'O' marking signifies that the product has been approved for the use both outdoors and indoors and the terminology used by Australian standards is 'outdoor un-tinted'. This marking appears on all clear, amber and contrast lenses
- O. Range of luminous transmittance 80-100% (clear).
- 3. Range of luminous transmittance 8 -18% (smoke).

APPLICATIONS

- Chemical splash protection
- Cutting
- Spraying
- Dust protection
- Acid and alkaline handling
- Wood and metal work

I ENSES

- 'ALS' anti-fog / anti-scratch coating on both sides of Clear and Smoke ventilated model lens
- 100% UV 385 Clear
- Platinum coating on sealed version Clear and Smoke Lens

CLEANING AND STORAGE

CLEANING: Bollé Safety recommends only using our **ECLEAN** Lens cleaning system.

MAINTENANCE: Pitted, scratched or damaged lenses must be replaced by replacing the complete product. If the frame is damaged also replace the complete product. After each use it is recommended to keep the spectacles or goggles in a microfiber pouch or rigid case.

STORAGE: Store between 5 and 40°, humidity <90%.

MAIN MARKETS

- Petro Chemical
- Construction
- Manufacturing
- Paint
- Automotive
- Labs

CHARACTERISTICS				
LENSES	PC - 2,2 mm - Curve 4			
FRAME	PVC			
STRAP	Nylon			
FOAM	No			
SPARE LENSES	No			

FRAME MARKING AS/NZS 1337.1.2010: Tested and approved to AS/NZS 1337.1.2010 for medium impact protection, splash protection, dust and gas protection. Resists a 6mm at 45 m/s. Meets the requirements of splash approval when used with the supplied

head strap correctly adjusted.

ASIA/PACIFIC HEADQUARTERS:

Bollé Australia Pty Ltd 32-40 Fairchild Street Heatherton VIC 3202 T: 1300 138 098 E: safety@bolle.com.au

NEW ZEALAND:

Bollé New Zealand Limited Unit 5, 114 Sawyers Arms Road Papanui, Christchurch 8052 T: 03 3751400 E: bolle@bolle.co.nz

